Appendix 1 – Extensions log for 2021

Date	Airline Code	Sch Time	Actual Time	Delay Time (mins)	Arr / Dep	Registration	Flight #	Airport	Runway	Delay code 1	Description 1	Delay code 2
03/01/21	EI	21.20	21.00	-288	A	EIFNA	3619	MAN		0	extension requested but not used - (noted here just for info)	
15/01/2021	EI	21:15	22:01	46	A	EIFSL	3679	LBA	22	71	WEATHER DEPARTURE STATION	
22/01/2021	EI	21:10	22:39	89	A	EIFNA	3649	BHX	22	71	WEATHER DEPARTURE STATION	
24/01/2021	EI	21:10	21:49	39	A	EIFNA	3648	BHX	22	75	DE-ICING OF AIRCRAFT, removal of ice and/or snow, frost prevention excluding unserviceability of equipment	
18/03/2021	EI	21:05	23:00	115	A	EIDVL	937	LHR		72	WEATHER DESTINATION STATION	
04/06/2021	EI	21:15	22:47	92	A	EIFNA	3659	EDI		96	OPERATIONS CONTROL, re-routing, diversion, consolidation, aircraft change for reasons other than technical	
06/06/2021	EI	21:10	22:32	82	A	EIFMJ	3649	BHX		96	OPERATIONS CONTROL, re-routing, diversion, consolidation, aircraft change for reasons other than technical	
06/06/2021	EI	21:15	23:19	124	A	EIFSK	3659	EDI		96	OPERATIONS CONTROL, re-routing, diversion, consolidation, aircraft change for reasons other than technical	
06/06/2021	EI	20:40	22:18	98	A	EIFNA	3689	EMA		96	OPERATIONS CONTROL, re-routing, diversion, consolidation, aircraft change for reasons other than technical	
11/06/2021	EI	21:15	23:00	105	A	EIFNA	3659	EDI		96	OPERATIONS CONTROL, re-routing, diversion, consolidation, aircraft change for reasons other than technical	
27/06/2021	LM	19:25	22:01	156	A	GSAJD	575	MME		93	AIRCRAFT ROTATION, late arrival of aircraft from another flight or previous sector	TECH IN MME
27/06/2021	LM	19:55	22:39	164	D	GSAJD	576	MME		93	AIRCRAFT ROTATION, late arrival of aircraft from another flight or previous sector	TECH IN MME
27/06/2021	FR	21:20	21:56	36	A	EIDLD	85P	STN		93	POSITIONING A/C WITH ENGINEER ON BOARD TO SIGN OFF TECH PMI IN BHD	
27/06/2021	FR	22:00	22:42	42	D	EIDLD	84P	STN		93	POSITIONING A/C WITH ENGINEER ON BOARD TO SIGN OFF TECH PMI IN BHD	
27/06/2021	FR	19:50	22:46	176	D	EIEVE	2440	PMI		41	AIRCRAFT DEFECTS.	
11/08/2021	EZY	20:05	22:21	136	D	GEZTC	704	LGW		66	LATE CABIN CREW BOARDING OR DEPARTURE PROCEDURES, other than connection and standby	
17/09/2021	BA	20:40	21:43	63	A	GLCYR	8758	LCY		64	FLIGHT DECK CREW SHORTAGE, sickness, awaiting standby, flight time limitations, crew meals, valid visa, health documents, etc.	
20/09/2021	BA	21:10	21:53	43	A	GLCAE	7330	GLA		41	AIRCRAFT DEFECTS.	
28/11/2021	BACF	2055	23:32	160	A	GLCYU	7324	BHX		75	AWAITING DEICING OF AIRCRAFT AT BHX	
03/12/2021	BACF	2055	22:16	81	A	GLCYV	7324	BHX		93	react delay due an earlier tech aircraft and delay ex BHD (BA7316 to LBA)	
19/12/2021	BA	2010	21:45	100	A	GEUPK	1422	LHR		93	LOADING / LACK OF LOADING STAFF LHR	
20/12/2021	T3	10:10	21:40	690	A	GMAJL	832	CWL		41	REAC due aicraft tech on most sectors	
22/12/2021	T3	19:05	22:04	179	A	GIACZ	846	SOU		41/87	TECH and ground handling issues in SOU	
28/12/2021	LM	1915	22:29	194	D	GRJXH	86	ABZ		93/89	LIAC AND ATC RESTRICTIONS HERE AT BHD - SINGLE MAN OPERATION	